

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

210609 CAS000 001286

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name BASF Wyandotte Corporation
Street P. O. Box 181
City Parsippany, State N.J. Zip Code 07054

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site DIVERSEY WYANDOTTE CORPORATION
Street 8921 Dice Road
City Santa Fe Springs County Los Angeles State CA Zip Code 90670

CAD046455747

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Kraemer, Wm., Mgr., Corp. Env. Protection
Phone (201) 263-5310

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1953 To (Year) 1974

E Waste Type

During the period of 1953 to 1974 approximately 15 shallow wells (40 ft.) were used on the Santa Fe Springs property for disposal. Waste solutions containing sodium hydroxide, sodium carbonate, phosphoric acid, and various vessel washings were injected into these wells. Some neutralization would have taken place in the underground. Operation occurred 5 days/week and volume only amounted to an average of 200 gal/day. Wells in 1974 were sealed by paving over with a parking lot.

This plant was sold to Diversey Wyandotte Corporation in 1979.

1 2 JUN 1981

(011)

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☒ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet _____

gallons 1,000,000 *G***Total Facility Area**

square feet _____

acres _____

See E, Front Page

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Dunn, R. E., Secretary of
BASF Wyandotte Corporation

Street P.O. Box 181

City Parsippany

State N. J. Zip Code 07054

Signature *Robert E. Dunn* Date 4/5/81

- ☐ Owner, Present
☒ Owner, Past
☐ Transporter
☐ Operator, Present
☒ Operator, Past
☐ Other

BASF Wyandotte Corporation



100 Cherry Hill Road
P.O. Box 181
Passippany, N.J. 07054
201/263-0200

Certified Mail
P29 2144639

June 5, 1981

U. S. EPA Region 9
Sites Notification
San Francisco, California 94105

Gentlemen:

Enclosed is the submission of hazardous waste site as required by Section 103(c) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980. The plant at Santa Fe Springs, California was formerly owned and operated by BASF Wyandotte Corporation.

Very truly yours,



Keith Fry, Director
Corporate Environmental
Protection

KF:if
enclosure